
RENISHAW
apply innovation™

Reporter for Siemens controls


Reporter is a simple, intuitive app for customers who wish to view component measurement data on the CNC machine tool control or tablet PC.

Thanks to the app's intuitive design, data is displayed in a way that is easy to understand; perfect for those with little or no probing experience. The graphical display provides a real-time pass or fail indication for each measurement while historical data allows the app to display measurement data for every part measured on that machine tool.









Benefits

- Quickly view pass and fail measurement data at the CNC machine tool
- Displays measurement trends for every measured component
- Measurement results can be viewed live, as the component is measured
- Enter custom naming conventions for components and measured features
- Minimal training and product documentation required

Renishaw plc

New Mills, Wotton-under-Edge
Gloucestershire, GL12 8JR
United Kingdom

T +44 (0) 1453 524524
F +44 (0) 1453 524901
E uk@renishaw.com

www.renishaw.com

RENISHAW
apply innovation™

Part number	A-5999-4700
Supported Siemens controls [1]	SINUMERIK 840D solutionline with PCU50 (Microsoft® Windows® OS)
Supported machine types	Horizontal machining centres, vertical machining centres
Hard disk requirements	
App alone	162 MB
.NET Framework	Approximately 850 MB (32-bit controls); approximately 2 GB (64-bit controls)
Supported cycles	
Inspection Plus cycles	X/Y/Z single surface, web, pocket, bore, boss, corner (internal), corner (external), 5-point rectangle (internal), 5-point rectangle (external), 3-point bore, 3-point boss, 4th axis measurement, angle XY plane
Reported feature measurements	
X, Y and/or Z position	X/Y/Z single surface, web, pocket, bore, boss, corner (internal), corner (external), 5-point rectangle (internal), 5-point rectangle (external), 3-point bore, 3-point boss
Diameter	Bore, boss, 3-point bore, 3-point boss
Width	Web, pocket
Edge angle	Angle XY plane, 5-point rectangle (internal), 5-point rectangle (external)
Internal angle	Corner (internal), corner (external)
A, B and/or C angle	4th axis measurement
Macro prerequisites (machining centres)	
Inspection Plus	Renishaw part no. A-4014-0356, **version 0H or later**
Supported Renishaw spindle probes	All current touch-trigger probes
Supported languages	Czech, English, French, German, Italian, Japanese, Korean, Polish, Portuguese, Russian, Simplified Chinese, Spanish, Swedish, Thai, Traditional Chinese, Turkish

[1] SINUMERIK 840D solutionline SINUMERIK INTEGRATE RUN MYHMI /3GL (Siemens part no. 6FC5800-0AP60-0YB0) must be enabled. Check licence page on the CNC. For other controls, please contact your local Siemens office.

For worldwide contact details, visit www.renishaw.com/contact

RENISHAW HAS MADE CONSIDERABLE EFFORTS TO ENSURE THE CONTENT OF THIS DOCUMENT IS CORRECT AT THE DATE OF PUBLICATION BUT MAKES NO WARRANTIES OR REPRESENTATIONS REGARDING THE CONTENT. RENISHAW EXCLUDES LIABILITY, HOWSOEVER ARISING, FOR ANY INACCURACIES IN THIS DOCUMENT.

© 2017 Renishaw plc. All rights reserved.
Renishaw reserves the right to change specifications without notice.
RENISHAW and the probe symbol used in the RENISHAW logo are registered trade marks of Renishaw plc in the United Kingdom and other countries.
apply innovation and names and designations of other Renishaw products and technologies are trade marks of Renishaw plc or its subsidiaries.
All other brand names and product names used in this document are trade names, trade marks or registered trade marks of their respective owners.

H-5999-8650-01

Part no.: H-5999-8650-01-A
Issued: 09.2017

RENISHAW
apply innovation™

Reporter for Fanuc controls


Reporter is a simple, intuitive app for customers who wish to view component measurement data on the CNC machine tool control or tablet PC.

Thanks to the app's intuitive design, data is displayed in a way that is easy to understand; perfect for those with little or no probing experience. The graphical display provides a real-time pass or fail indication for each measurement while historical data allows the app to display measurement data for every part measured on that machine tool. Reporter displays probe measurement data from Inspection Plus programs: both those that have been programmed directly and those generated via the Set and Inspect app.









Benefits

- Quickly view pass and fail measurement data at the CNC machine tool
- Displays measurement trends for every measured component
- Measurement results can be viewed live, as the component is measured
- Enter custom naming conventions for components and measured features
- Complementary to the Set and Inspect app
- Minimal training and product documentation required

Renishaw plc

New Mills, Wotton-under-Edge
Gloucestershire, GL12 8JR
United Kingdom

T +44 (0) 1453 524524
F +44 (0) 1453 524901
E uk@renishaw.com

www.renishaw.com

RENISHAW
apply innovation™

Part number	A-5999-4200
Supported Fanuc controls [1]	0*i*-B/C/D, 16*i*, 18*i*, 30*i* 0*i*-F*i*, 15-*i*, 21*i*, 31*i*, 32*i*
Supported machine types	Horizontal machining centres, vertical machining centres
Hard disk requirements	
App alone	127 MB
.NET Framework	Approximately 850 MB (32-bit controls); approximately 2 GB (64-bit controls)
Supported cycles	
Inspection Plus cycles	X/Y/Z single surface, web, pocket, bore, boss, corner (internal), corner (external), line, 5-point rectangle (internal), 5-point rectangle (external), 3-point bore, 3-point boss, 4th axis measurement, angle XY plane
Set and Inspect: Program builder cycles	Single surface, bore, boss, pocket, web, corner (internal), corner (external), line, 5-point rectangle (internal), 5-point rectangle (external), 3-point bore, 3-point boss, rotary axis update
Reported feature measurements	
X, Y and/or Z position	X/Y/Z single surface, web, pocket, bore, boss, corner (internal), corner (external), 5-point rectangle (internal), 5-point rectangle (external), 3-point bore, 3-point boss
Diameter	Bore, boss, 3-point bore, 3-point boss
Width	Web, pocket
Edge angle	Angle XY plane, 5-point rectangle (internal), 5-point rectangle (external)
Internal angle	Corner (internal), corner (external)
A, B and/or C angle	4th axis measurement
Macro prerequisites	
Inspection Plus	Renishaw part no. A-4012-0516, **version AA or later**
Supported Renishaw spindle probes	All current touch-trigger probes
Set and Inspect compatibility	Renishaw part no. A-5999-1200, **version 2.1.1 or later**
Supported languages	Czech, English, French, German, Italian, Japanese, Korean, Polish, Portuguese, Russian, Simplified Chinese, Spanish, Swedish, Thai, Traditional Chinese, Turkish

[1] Fanuc NC with FOCAS or FOCAS 2. Microsoft® Windows®-based PC; Windows® XP, SP 3 or later: or tablet; Windows® 8 or later. Connection to the control is via Ethernet. For other controls, please contact your local Fanuc office.

For worldwide contact details, visit www.renishaw.com/contact

RENISHAW HAS MADE CONSIDERABLE EFFORTS TO ENSURE THE CONTENT OF THIS DOCUMENT IS CORRECT AT THE DATE OF PUBLICATION BUT MAKES NO WARRANTIES OR REPRESENTATIONS REGARDING THE CONTENT. RENISHAW EXCLUDES LIABILITY, HOWSOEVER ARISING, FOR ANY INACCURACIES IN THIS DOCUMENT.

© 2017 Renishaw plc. All rights reserved.
Renishaw reserves the right to change specifications without notice.
RENISHAW and the probe symbol used in the RENISHAW logo are registered trade marks of Renishaw plc in the United Kingdom and other countries.
apply innovation and names and designations of other Renishaw products and technologies are trade marks of Renishaw plc or its subsidiaries.
All other brand names and product names used in this document are trade names, trade marks or registered trade marks of their respective owners.

H-5999-8600-01

Part no.: H-5999-8600-01-A
Issued: 09.2017