# 100/200/300/400 USB OUTPUT INTERFACE

- The cable without software, push the black button or footswitch, the data can be transferred into Excel, Word directly.
- The cable with software, the data can be transferred into the software at a set interval time automatically.




100-11

VIDEO




Software




| Code | Software | Plug to product | Products |
|---|---|---|---|
| 100-03 | Without |  | for digital calipers with following electronics  |
| 100-04 | With | | |
| 100-03L | Without |   | for digital height gage with following electronics  |
| 100-04L | With | | |
| 100-11 | Without |  | for digital calipers with following electronics  |
| 100-12 | With | | |
| 100-15 | Without |  | for digital calipers and height gage with following electronics  |
| 100-17 | Without |  | for digital calipers with following electronics  |
| 200-03 | Without |  | for digital indicators with following electronics  |
| 200-04 | With | | |

*Confirm the electronics output port type when placing orders

| Code | Software | Plug to product | Products |
|---|---|---|---|
| 200-01 | Without |  | for digital indicators with following electronics  |
| 200-02 | With |  | |
| 300-03 | Without |  | for digital micrometers with data output with following electronics  |
| 300-04 | With | | |
| 300-51 | Without |  | for digital micrometers with data output with following electronics  |

Connect foot switch to transfer the data (code: **400-01**)



| Code | Name |
|---|---|
| 400-01 | foot switcht |