Usb Data Output Cable



Description

- Connect to USB port of computer
- Without software, measuring data can be input as keyboard signal to EXCEL,WORD...
- Press the button to input data, Packed in cardbox

Art No.	Barcode	Description
WP-DCA1	6972727950828	for digital calipers, digital micrometers, digital indicators
WP-DCA2	6972727950835	for digital indicators
WP-DCA3	6972727950842	for digital height gauge

Data Output Cable





Description

- Connect to RS232 9pin port of computer
- Supplied analog data acquisition software
- Support manual single data acquisition and automatic continuous data acquisition
- Packed in cardbox

Art No.	Barcode	Description
WP-DCB1	6972727950859	for digital calipers, digital micrometers, digital indicators
WP-DCB2	6972727950866	for digital indicators
WP-DCB3	6972727950873	for digital height gauge

Foot Switch

Art No.	Barcode
WP-FS01	6972727950880



WERKA
Single Channel Data Transmission (With Cable)

