



| ISO | R | L | H1 H | B | F | L1 | L2 | λS | Y0 | Insert | Shim | Screw | Screw | Torx Key |
|---------|---|---|---------|----|----|-----|----|----|----|-------------|---------|------------------|---------|----------|
| 1028600 | • | • | 8 | 8 | 10 | 100 | 16 | 0 | 0 | DC.T 0702.. | | | M2,5X7 | T08 |
| 1028700 | • | • | 10 | 10 | 12 | 100 | 16 | 0 | 0 | | | | | |
| 1028800 | • | • | 12 | 12 | 16 | 100 | 20 | 0 | 0 | | | | | |
| 1028900 | • | • | 16 | 16 | 20 | 100 | 25 | 0 | 0 | | | | | |
| 1029000 | • | • | 16 | 16 | 20 | 100 | 25 | 0 | 0 | DC.T 11T3.. | DC..011 | M5X- 0.5XM3.5 | M3,5X14 | T15 |
| 1029100 | • | • | 20 | 20 | 25 | 125 | 35 | 0 | 0 | | | | | |
| 1029200 | • | • | 25 | 25 | 32 | 150 | 40 | 0 | 0 | | | | | |
| 1029300 | • | • | 32 | 32 | 40 | 170 | 40 | 0 | 0 | | | | | |