



ISO	R	L	H1 H	B	F	L1	L2	λS	Y0	Insert	Shim	Screw	Screw	Torx Key
1024200	•	•	12	12	20	100	20	0	0	VBM. 1103..	-	-	M2,5X7	T08
1024300	•	•	16	16	20	100	25	0	0		-	-		
1024400	•	•	16	16	20	100	25	0	0	VBM. 1604..	-	-	M3,5X11	T15
1024500	•	•	20	20	25	125	35	0	0	VBM. 1103..	-	-	M2,5X7	T08
1024600	•	•	20	20	25	125	35	0	0	VBM. 1604..	VB..016	M5X- 0.5XM3.5	M3,5X14	T15
1024700	•	•	25	25	32	150	40	0	0					
1024800	•	•	32	32	40	170	40	0	0					
1024900	•	•	25	25	32	150	40	0	0	VBM. 1103..	-	-	M2,5X7	T08